

Stage 1: Initial Cavity Formation




FIG. 2a - 1

FIG. 2a - 2




FIG. 2b - 2




FIG. 2c - 2

Injection Well

Stage 2: Cavity Formation across Shale Partings





FIG. 2b - 1

Stage 3: Tubing Pull-Back or Perforation to Extend Cavity

Injection Well



Cross Section